

B	I	N	G	O
Use caution when working with solvents	Report injury to Lead/Supervisor	Food and drinks are to remain away from the production area	Reporting all injuries helps ISC become a safer healthier place to work for everyone	Know your surroundings
Empty trash cans on a regular basis	Store chemicals correctly	Operate equipment only if qualified and trained	Always wear safety glasses	Sleeping on the job is not prohibited
Beware of nozzle direction when using mold release spray	Keep walk areas and exits clear of items	Know machine operating procedures	Shut down machines when not in use	Know where the fire exits are
Report issues and keep organized all power and extension cords	In the case of eye irritation please use the eye cleaning stations located in the lunchroom and near shipping	Lift with your knees not your back	In an emergency use the safety shutoff button on molding machines	Do not let epoxies or glues make contact with your skin or clothing
Don't modify machinery	Most slips can be stopped by keeping the work area clean	Equipment should be kept away from the edges of workstations to avoid falling	Report all issues with machines: Example oil leaks	Use the right tool for the job

B	I	N	G	O
Safety is a state of mind and requires constant vigilance and common sense	Report issues and keep organized all power and extension cords	Operate equipment only if qualified and trained	Shut down machines when not in use	Do not let epoxies or glues make contact with your skin or clothing
Don't modify machinery	Report all issues with machines: Example oil leaks	Lift with your knees not your back	Empty trash cans on a regular basis	Most slips can be stopped by keeping the work area clean
Always wear safety glasses	Keep walk areas and exits clear of items	Report injury to Lead/Supervisor	Know your surroundings	Use caution when working with solvents
When purging plastic from mold machines use caution	Use the right tool for the job	Equipment should be kept away from the edges of workstations to avoid falling	Beware of nozzle direction when using mold release spray	Reporting all injuries helps ISC become a safer healthier place to work for everyone
Follow the proper test procedure for Hi-pot testing	Know machine operating procedures	Food and drinks are to remain away from the production area	In the case of eye irritation please use the eye cleaning stations located in the lunchroom and near shipping	The most common injuries for lifting are with your back

B	I	N	G	O
Equipment should be kept away from the edges of workstations to avoid falling	Shut down machines when not in use	Know where the fire exits are	Reporting all injuries helps ISC become a safer healthier place to work for everyone	Report injury to Lead/Supervisor
Use the right tool for the job	Food and drinks are to remain away from the production area	Don't modify machinery	Lift with your knees not your back	Know machine operating procedures
Keep body parts away from moving parts on machinery	Use caution when working with solvents	Beware of nozzle direction when using mold release spray	Sleeping on the job is not prohibited	Always wear safety glasses
Do not let epoxies or glues make contact with your skin or clothing	Follow the proper test procedure for Hi-pot testing	Store chemicals correctly	Keep walk areas and exits clear of items	Know your surroundings
Report issues and keep organized all power and extension cords	Empty trash cans on a regular basis	In an emergency use the safety shutoff button on molding machines	Report all issues with machines: Example oil leaks	Most slips can be stopped by keeping the work area clean